




PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE

Memo No. :13 /BDO/Bishnupur-II

Date : 04.01.2023

It is certified that an inspection team headed by Jadupati Das , Junior Engineer (RWS) from Bishnupur-II Development Block inspected the Delhi Public School (Joka) South Kolkata, Gazipur (Keyatalahat) Bakhrahat Road, P.S.- Bishnupur. Dist.- South 24 Parganas, PIN-743503, on 05.12.2022 and found that the Delhi Public School (Joka) South Kolkata has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T. Govt.

The above is valid for a period of 01(One) year only.

Signature with seal : 
Name : UTPAL MUKHERJEE
Designation : BLOCK DEVELOPMENT OFFICER
BISHNUPUR-II DEV. BLOCK

Block Development Officer
Bishnupur - II
South 24 Parganas

To
The Principal
Delhi Public School (Joka) South Kolkata
Gazipur (Keyatalahat) Bakhrahat Road,
P.S.- Bishnupur. Dist.- South 24 Parganas,
PIN-743503,